

Notice

SANYO

CORRECTION
 SERVICE FLASH

PRODUCTION CHANGE
 ADD INFORMATION

FILE NO.

Please add this notice to the Service Manual listed below.

Category: COLOR TELEVISION

Date: OCTOBER / 06 / 2009

Model: DP37649

Effective from : Chassis No. P37649-01

Destination: U.S.A. / CANADA

REF : No. SM780162-01

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. If the Service Manual Chassis No. does not match the unit's, additional Service Literature is required. This chassis is similar to Chassis No. P37649-00. Only the difference Service Information is given in this manual. For detailed Service Information, refer to the Original Service Manual and Notices for Chassis No. P37649-00 used in Model DP37649 (SM7800162).

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

PAGE 4 ON-SCREEN SERVICE MENU

Item No. 088 OP2 Data should match 21h in the table and in Note 2.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

A : Misprint B : Quality Reliability

C : Standardization

D : Design E : Add as a possible sub

F : Schematic location change

G : Purchasing Request

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchangeability	Reason
Page 25, Chassis Electrical Parts List	▲ EL901	Old	1AV4T40C11900	LCD(T370XW02 VC02)	1	NO	
		New	1AV4T40C00300	LCD(T370XW02 VC00)	1	NO	D

For parts or service contact:

Sanyo Manufacturing Corporation
P.O. Box 2000
3333 Sanyo Road
Forrest City, Arkansas 72335-2000